

	Type	L #	Hits	Search Text
1	BRS	L1	1	"6663187".pn.
2	BRS	L2	1	"4775919".pn.
3	BRS	L3	67	wheel same spinner same motor
4	BRS	L4	130	wheel same spinner with motor
5	BRS	L5	2	"4775919".pn.
6	BRS	L6	2	"5188428".pn.
7	BRS	L7	2	"5659989".pn.
8	BRS	L8	2	"5931543".pn.
9	BRS	L9	2	"6070947".pn.
10	BRS	L10	2	"6116763".pn.
11	BRS	L11	2	"6322237".pn.

	DBs	Time Stamp	Comments	Error Definition	Errors
1	USPAT	2005/07/19 09:16			
2	USPAT	2005/07/19 09:23			
3	USPAT	2005/07/19 09:52			
4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 09:37			
5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 09:37			
6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 09:45			
7	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 09:46			
8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 09:46			
9	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 09:47			
10	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 09:48			
11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 09:48			

	Type	L #	Hits	Search Text
12	BRS	L12	2	"6464303".pn.
13	BRS	L13	2	"6554370".pn.
14	BRS	L14	39	( "1432274"   "2130220"   "2548070"   "2727790"   "2762469"   "2869262"   "2935361"   "2997344"   "3158946"   "3219391"   "3457663"   "3495347"   "3722958"   "3810679"   "5016944"   "5190354"   "5286092"   "5290094"   "5490342"   "5584537"   "5588715"   "5659989"   "5957542"   "6045195"   "6120104"   "D303103"   "D424502") .PN.
15	BRS	L15	8	("6120104") .URPN.
16	BRS	L16	158	wheel same spinner with (motor or clutch)
17	BRS	L17	0	"10831104".pn.
18	BRS	L18	0	"11831104".pn.

	DBs	Time Stamp	Co mm en ts	Er ro r De fi ni ti on	Err ors
12	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 09:48			
13	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 09:48			
14	US-PGPUB; USPAT; USOCR	2005/07/19 09:49			
15	USPAT	2005/07/19 09:51			
16	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 10:54			
17	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 10:55			
18	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 10:55			

	Type	L #	Hits	Search Text
19	BRS	L19	2	"20050052069".pn.
20	BRS	L20	62	301/37.25
21	BRS	L21	27	301/37.108
22	IS&R	L22	110	(301/37.25) .CCLS.
23	IS&R	L23	39	(301/37.108) .CCLS.
24	IS&R	L24	38	(301/37.102) .CCLS.
25	IS&R	L25	127	(301/37.101) .CCLS.
26	IS&R	L26	372	(40/587) .CCLS.

	DBs	Time Stamp	Comments	Error Definition	Errors
19	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 11:03			
20	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 11:03			
21	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 11:03			
22	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 11:07			
23	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 11:15			
24	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 11:17			
25	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 11:18			
26	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/07/19 11:21			